


# Audit Findings



# Audit Findings


The Most Common Audit Items

**Topping the list...** 





# Audit Findings





Plans are Incomplete



#### Coordination

#### **Responsibility for Coordination of Plans**

- Phoenix Building Construction Code Section 107.3.4 Design Professional in responsible charge
- Prime Professional per Arizona Administrative Code R4-30-101
- The Self-Certifier
- YOU



# Complete Drawings

- Provide the Project Scope BE SPECIFIC
- Code Modifications
- Fire Department Appeals
- Special Inspection Certificates
- Deferred Submittals





# Coordination

- Plan Sheets
- Detailing
- Coordination between architectural and engineering drawings





# **Technical Accuracy**

- Checklists (TRT documents online)
- Meet with consultants
- Read the codes
- Use the Code Commentaries
- CALL US!!!







#### Plan Review Checklist Architectural

#### ARCHITECTURAL DRAWINGS

Sealed by an architect registered in the State of Arizona.

2012 International Building Code (IBC) & other 2012 International Code Council (ICC) Codes referenced herein, with Phoenix Amendments, 2009 ICC/ANSI A117.1, 2010 ADA Standards), 2012 International

EII	ergy Conservation Code
1.	General Architect's seal, signature, date signed & date of seal expiration, IBC 107.2.1 & State Board Rules Use and Occupancy Classification, Chapter 3 Type of Construction, Chapter 6 Fire-Resistance Requirements, Table 601 Exterior Wall Rating & Fire Separation Distance, Table 602 Opening protectives, 716 Architectural Site Plan Property lines shown, match Quarter Section map, replat Imaginary property lines shown, 705.3 Site accessible route 1104.1 Between buildings and on site 1104.2
2.	Building Height & Area, IBC Chapter 5  Allowable height & area, IBC Table 503  Area increases, 506  Unlimited area, 507  Height increases, 504  Parking beneath occupancies (podium bldg concept), 510 Special Provisions  Use of firewall to create separate buildings 706  Mixed use and occupancy, 508  Non-separated, 508.3  Separated, 508.4
3.	Accessibility See Accessibility Plan Review Checklist for a broader list Accessibility Chapter 11, 3411, ICC/ANSI A117.1, 2010 ADA Standards for Accessible Design Elevators, 1007.2.1, 1007.4
4.	Fire-Resistance-Rated Construction  Fire resistive assemblies shown, 703.3  Special Inspection Certificate required for spray applied fire proofing, 1705.13  Mastic/intumescent, 1705.14  % protected opening vs. unprotected, Table 705.8  Fire rated control joints, 715, 705.9  Projections related to the property line, 705.2  Occupancy separation 508, Table 508.4  Structural members, 704  Fire walls, 706  Fire barriers, 707  Shafts enclosures, 713  Opening protectives, 716  Flexible ducts/air connectors not allowed, 717.7

Page 1 of 3

This publication can be made available in alternate formats (Braille, large print, computer diskette, or audiotape) upon request. Contact Planning and Development at (602) 262-7811 voice or (602) 534-5500 TTY. TRT/DOC/00711


#### City of Phoenix Planning and Development Department Plan Review Checklist, Architectural - Page 2 of 3

TRT/DOC/00711


5.	Special Uses & Occupancies, Chapter 4  Covered Malls, 402  High-rise buildings, 403  Atriums, 404  Underground buildings, 405  Garages, 406  Public parking garage, 406.4  Open parking garage, 406.5  Enclosed parking garage, 406.6  Parking beneath occupancies (podium bldg concept), 510  Repair garages, 406.8  Flammable gas detection system for hydrogen & nonodorized LNG repair garages, 406.8.5  Group I-2 Hospitals, 407  Stages and Platforms, 410  Special Amusement Buildings, 411  Combustible Storage, IBC 413, International Fire Code (IFC) with Phoenix Amendments  High-piled stock  Rack storage  Attic, under-floor and concealed spaces
6.	Smoke & Fire Control  Smoke Control Systems Required, IBC/IFC 909  Fire/Smoke dampers 717  Corridors, 717.5.4.1  Ducts and air transfer openings, IBC/IFC 909.5.2.1  Smoke and Heat Vents, IBC/IFC 910  Increased travel distance Group F-1 or S-1, IBC/IFC ?????  Ducts and Air Transfer Openings, 717
7.	Exterior Walls & Roofs   Imaginary property lines shown, 705.3   Parapets 705.11   Fire wall at exterior wall, 706.5.1   Stepped buildings, 706.6.1   Ducts & air transfer openings penetrating fire-rated exterior walls, 717.5.6   Combustible materials on the exterior side of exterior walls, 1406   Veneer 1405.10   Adhered veneer requires Special Inspection above 8', special cases   ICBO# (skylight, EIFS, 1 coat stucco)   Roof classification, Table 1505.1.   Roof slopes 1507 varies by material (BU10, mod bit .11, Thermoset .12, TPO .13, poly U .14, Liquid .15)   Roof drain & overflow 1503.4 (now in IPC)   Access to rooftop equipment/appliances required, IMC 306.5   Stainway to roof, 1009.16
8.	Interior Walls, Floors, Attics  Veneer 1405.10  Adhered veneer requires Special Inspection above 8', special cases  Wall finishes, flame spread, 803, Table 803.9  Toilet room walls and floors, 1210  Gypsum board in showers and water closets, 2509  Kitchen hood separation, IMC 506.3.10 / IBC 713  Fire blocking 718.2  Draft stops  Floors 718.3  Attics 718.4  Attic ventilation 1203.2  Attic access 1209.2



# **Residential Audits**



## **Commercial Audits**



### **Architectural Comments**

- Providing a complete architectural site plan; showing fire separation distances, projection distances, exterior wall openings allowed, path of exit discharge and accessible routes
- Showing the means of egress in sufficient detail; all components sized, number of occupants in each space
- Providing adequate fire-resistance rated detailing with actual listed assemblies and openings, joints and penetrations



### Structural Comments

- Deferral of stair and guardrail design
- Showing all of the required design data from IBC Section 1603.1
- Providing a lateral force resisting system that is adequately detailed on the drawings and supported in the calculations to justify a complete load path



# Mechanical/Plumbing Comments

• Civil drawings do not match plumbing drawings. Meter sizes and water and sewer line sizes are not coordinated.

Missing or incorrect outside air mechanical ventilation calculations

Incomplete information regarding Type 1 exhaust hoods



### Fire Comments

- Inadequate hazardous materials and processes evaluation
- Listing of deferred life safety submittals; distinguishing NFPA 13 and 13R fire sprinkler systems




### **Electrical Comments**

- Fault current calculations
- Load calculations
- Electrical feeder sizing
- Grounding/bonding
- Healthcare-related occupancies; complex electrical systems
- Electrically classified (hazardous) locations



### **Civil Comments**

- Address zoning stipulations
  - Include all zoning action stipulations
  - Consistency with the preliminary site plan
- Coordinate site, civil & landscape plan





### Successful Plans

Ingredients for a successful audit include....



**Quality Control** 



**Complete and Coordinated Plans** 

**Technical Accuracy** 



# Questions



